

---

## Compliance Inspection Report: March 2021

---

**RM File No:** RM150184

**Description of Activity:** Extraction of gravel, removal of indigenous vegetation and associated earthworks

**Consent Holder:** GBC Winstone Aggregates

**Inspection Dates:** Site inspections:  
5 March 2021

---

### Compliance Summary

1 resource consent inspection has occurred since the last CLG.

0 service requests have been received.

### Points of Discussion

- One inspection occurred during this time frame.
- Acoustic Bund was in good condition, mowed and minimal weeds present.
- Area of bund where there was a slump has been stabilised and now has good growth which has binded the area well.
- Cypress hedge planting at the rear of the bund have good growth and replacement planting is doing well.
- Excavation is progressing well and to date no complaints regarding consent have been logged.
- Stockpiles of topsoil on southern boundary have been reduced a good degree of the material has been used to prepare the southern bank for planting later.
- The remaining material has been stabilised and as discussed at previous meetings does not cause an issue.
- Rehabilitation planting is ahead of schedule and plantings now extend around parts of Stage 1B as well as 1A, plant survival looking good.
- Council's Infrastructure Team will make the decision regarding the requirements around access on paper road, which is to be decided once the expressway is completed.

**Signed**

**Simon Amos**  
**RMA Compliance**

Stage 1A and 1B.To the

press trees that had died.



Below

d 1B.





Stage 2 – Topsoil placed ready for landscaping and at later planting on the Southern side (top photo) and Western (bottom photo)

