

---

## Compliance Inspection Report: September 2021

---

<b>RM File No:</b>	RM150184
<b>Description of Activity:</b>	Extraction of gravel, removal of indigenous vegetation and associated earthworks
<b>Consent Holder:</b>	GBC Winstone Aggregates
<b>Inspection Dates:</b>	<u>Site inspections:</u> 20 September 2021

---

### **Compliance Summary**

1. Resource consent inspection has occurred since the last CLG.

No Service requests logged into Council system. (Complaints)

### **Points of Discussion**

- One inspection occurred during the last six months.
- Acoustic Bund has good growth and the grass mound is to be mowed within the next few weeks.
- Weed spraying was carried out late July – August.
- Cypress hedge planting at the rear of the bund has good growth and replacement planting is doing well.
- As Winstones report states excavation is progressing well and to date no complaints received regarding consent conditions.
- Topsoil is in the process of being placed in areas that have been worked along the edges of excavated areas.
- The remaining material has been stabilised and as discussed at previous meetings does not cause an issue.
- Rehabilitation planting is looking good no major plant loss.

**Signed**

**Simon Amos**  
**RMA Compliance**

Stage 1A and 1B. To the left of the bund are the replacement planting of Cypress trees that had died.





Below good growth for planting on the banks Sage 1A and 1B.





Stage 2. – Gravel extraction in progress to form the pond with first stage of planting on yet to be formed island.

